



*Orkney Surveying Services*

**Billy Groundwater** AssocRICS  
Quantity Surveyor and Project Manager

Castlehowe, Sower Rd, Orphir, Orkney, KW17 2RE  
Mob: 07585447329 Tel: 01856811765

Web: [www.orkneysurveying.co.uk](http://www.orkneysurveying.co.uk)  
Email: [billy@orkneysurveying.co.uk](mailto:billy@orkneysurveying.co.uk)

# Home Report

**Burnside  
Cusbay Road  
Eday  
Orkney  
KW17 2AB**



*Orkney Surveying Services*

**Billy Groundwater** AssocRICS  
Quantity Surveyor and Project Manager

Castlehowe, Sower Rd, Orphir, Orkney, KW17 2RE  
Mob: 07585447329 Tel: 01856811765

Web: [www.orkneysurveying.co.uk](http://www.orkneysurveying.co.uk)  
Email: [billy@orkneysurveying.co.uk](mailto:billy@orkneysurveying.co.uk)

Our services include:

Quantity Surveying

Project Management

Property Valuations

Deed Plans

Home Reports:

Single Survey

Energy Performance Certificate

Mortgage Valuation Report

Energy Performance Certificates – domestic & commercial

SAP Assessments

For further information on any of these services please contact us on

(01856 811765) or (07585 447329)

or

[billy@orkneysurveying.co.uk](mailto:billy@orkneysurveying.co.uk)

# Home Report



**Property address:** Burnside  
Eday  
Orkney  
KW17 2AB

**Customer:** Florence Sayers

**Address:** c/o Burnside  
Eday  
Orkney  
KW17 2AB

**Date of inspection:** 28<sup>th</sup> October 2025

## 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without the need to move any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right are taken facing the front of the property.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. were not inspected or reported on.

|                                                  |                                                                                                                                                                                                                                                                                                |
|--------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Description</b>                               | A detached cottage with outbuildings, sitting within a strip of land stretching from the shoreline up to the public road. Total area is approximately 6.5 acres.<br>It is understood that the property is a registered croft, but that the site of the dwelling and garden has been decrofted. |
| <b>Accommodation</b>                             | Sitting Room, Kitchen, Bedroom, Shower Room, Hall.                                                                                                                                                                                                                                             |
| <b>Gross internal floor area (m<sup>2</sup>)</b> | The gross internal floor area of the dwelling is approximately 75m <sup>2</sup> .                                                                                                                                                                                                              |
| <b>Neighbourhood and location</b>                | The property is situated in a rural location in Eday, which is one of Orkney's north isles.<br>Eday has a Primary School and community shop and is well connected to the Orkney Mainland by regular sea and air services.                                                                      |
| <b>Age</b>                                       | The original property is likely to date from the early Twentieth Century, with various additions over the years.                                                                                                                                                                               |
| <b>Weather</b>                                   | The weather was cool and bright, following a period of changeable weather.                                                                                                                                                                                                                     |

### Chimney stacks

There are 2nr chimney stacks.  
The chimney stack to the south-west gable of the original stone-built section of the house is assumed to be stone-built and is harled with a concrete cope and a single clay chimney can.  
There is also a chimney stack to the extension, which is assumed to be block-built. This chimney stack also has a concrete cope and a single clay chimney can.  
There are no leadwork flashings to the chimneys.

*Visually inspected with the use of binoculars **where appropriate**.*

### Roofing including roof space

Pitched timber framed roof structure to the original cottage and the extension, clad with timber sarking boards and pointed Caithness slates.  
Concrete ridge and concrete skews; there are no leadwork flashings to the concrete skews.  
Thin polystyrene insulation to the ceiling joists.

*Sloping roofs were visually inspected with the aid of binoculars **where appropriate**.*

*Head and shoulders inspection of the roof space only.*

### Rainwater fittings

uPVC gutters and down pipes.

*Visually inspected with the aid of binoculars **where appropriate**.*

### Main walls

Stone walls to the original part of the property; block walls to the extension.

*Visually inspected with the aid of binoculars **where appropriate**.*

*Foundations and concealed parts were not exposed or inspected.*

### Windows, external doors and joinery

uPVC double glazed windows and external doors.  
Timber door between the house and store.  
Timber fascia boards.

*Internal and external doors were opened and closed where keys were available.*

*Random windows were opened and closed where possible.*

*Doors and windows were not forced open.*

### External decorations

The timber fascia boards, and the door between the house and the store, are painted.  
External walls are painted.

*Visually inspected.*

### Conservatories / porches

Porches to the front and rear elevations.  
Both porches consist of concrete floors, timber framed and block walls, flat roofs clad with fibre cement sheeting (note: the sheeting may contain asbestos, depending on their age), uPVC windows and doors.

*Visually inspected.*

### Communal areas

The hard-cored track from the public road to the edge of the property is shared with the neighbouring property.

*Circulation areas visually inspected.*

### Garages and permanent outbuildings

Storeroom attached to the eastern gable of the house.  
Concrete floor, block walls, mono-pitch roof clad with fibre cement sheets, timber windows and external door.

Separate detached store building to the south of the house.  
Timber framed walls, pitched roofs clad with fibre cement sheets, timber doors and windows.

Note: the fibre cement sheets may contain asbestos, depending on their age.

*Visually inspected.*

### Outside areas and boundaries

Grassed areas around the house, extending down to the shoreline.

Grass track down from the access road which is shared with the neighbouring property.

The property includes the farmland between the house and the public road; post & wire fencing to the boundaries; the approximate dimensions of the land (as estimated off plan) are 315m x 85m.

It is understood that a small area incorporating the 'Site of the dwelling house and garden' and measuring 18.8m x 8.7m were decrofted in 2004.

*Visually inspected.*

### Ceilings

The ceilings appear to be lined with hardboard.

*Visually inspected from floor level.*

### Internal walls

Interior walls and partitions are lined with plasterboard or OSB.

*Visually inspected from floor level.*

*Using a moisture meter, walls were randomly tested for dampness where considered appropriate.*

### Floors including sub floors

Solid concrete ground floor.

*Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.*

*There are no sub-floor areas.*

### Internal joinery and kitchen fittings

Fitted floor units to the Kitchen.

Plywood interior doors.

Softwood timber finishes.

Plywood window cills and ingoes.

*Built-in cupboards were looked into but no stored items were moved.*

*Kitchen units were visually inspected excluding appliances.*

### Chimney breasts and fireplaces

There are no chimney breasts or fireplaces.

*Visually inspected. No testing of the flues or fittings was carried out.*

### Internal decorations

Internal walls and ceilings are painted or wallpapered.

Interior woodwork is painted.

Wall tiles to the Shower Room.

Floor finishes include vinyl and floor tiles.

*Visually inspected.*

### Cellars

There are no cellars.

*Visually inspected where there was safe and purpose-built access.*

### Electricity

The property is served by a mains electricity supply to a distribution board and dual tariff meters (labelled as THTC) on a board in the Hall.

*Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.*

### Gas

There is no mains gas in Orkney.  
No Calor Gas installation at the property.

*Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.*

### Water, plumbing and bathroom fittings

There is a mains water supply to the property.  
The pipework, where visible, is of copper and uPVC construction.  
Sanitary ware includes:  
Kitchen: single bowl sink and drainer.  
Shower Room: electric shower with shower curtain, above a dished area of floor, wash-hand basin, WC.  
Plastic cold water header tank in the roof space.

*Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.  
No tests whatsoever were carried out to the system or appliances.*

### Heating and hot water

The house is heated by an electric storage heater in the Hall, a storage/convactor heater in the Sitting Room, and a panel heater in the Bedroom.

Hot water is assumed to be supplied by an electric immersion in the hot water cylinder, which is in a cupboard in the Kitchen.

*Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.  
No tests whatsoever were carried out to the system or appliances.*

### Drainage

Drainage is assumed to connect to a private septic tank on site, although this could not be seen at the time of inspection.

*Drainage covers etc were not lifted.  
Neither drains nor drainage systems were tested.*

### Fire, smoke and burglar alarms

No smoke detectors were noted at the time of inspection.

*Visually inspected.  
No tests whatsoever were carried out to the system or appliances.*



**Any additional limits to inspection:**

*At the time of our inspection the property was unoccupied and partly furnished with floors mainly covered.*

*Pitched roof coverings were inspected from ground level; a detailed inspection of condition was not undertaken.*


*An inspection for Japanese Knotweed or other invasive plant species was not carried out.*

*There was no access for inspection to the foundations or behind wall linings.*

*The drainage system was not open to inspection.*

*High levels of Radon gas have been recorded in areas of Orkney. No tests were carried out to detect the levels of gas in the property.*

## Sectional diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these terms.

## 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of three categories.

| Category 3                                                                                                                                                                                               |                                                                                                                                                                       | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. |                                                                                                                                                                       | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |
|  <b>Structural movement</b>                                                                                             |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category                                                                                                                                                                                          | 2                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Cracks noted to external walls.                                                                                                                                       |                                                                                     |                                          |
|  <b>Dampness, rot and infestation</b>                                                                                   |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category                                                                                                                                                                                          | 3                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Extensive rodent infestation noted at the time of inspection.<br>Dampness noted throughout.<br>Signs of woodworm activity noted to the roof timbers.                  |                                                                                     |                                          |
|  <b>Chimney stacks</b>                                                                                                 |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category:                                                                                                                                                                                         | 3                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Cracks noted to the chimney cans and stacks.<br>No leadwork flashings to the bases of the chimneys.<br>Cracks also noted to the chimney stacks within the roof space. |                                                                                     |                                          |
|  <b>Roofing including roof space</b>                                                                                  |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category:                                                                                                                                                                                         | 2                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Slipped slates noted; cracked and missing pointing to the roof slates.<br>Cracks noted to concrete skewers.                                                           |                                                                                     |                                          |
|  <b>Rainwater fittings</b>                                                                                            |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category:                                                                                                                                                                                         | 3                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Gutters are broken and sagging; vegetation build-up noted to the gutters.                                                                                             |                                                                                     |                                          |
|  <b>Main walls</b>                                                                                                    |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category:                                                                                                                                                                                         | 3                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Significant cracks noted to walls and external ingoes                                                                                                                 |                                                                                     |                                          |
|  <b>Windows, external doors and joinery</b>                                                                           |                                                                                                                                                                       |                                                                                     |                                          |
| Repair category:                                                                                                                                                                                         | 2                                                                                                                                                                     |                                                                                     |                                          |
| Notes:                                                                                                                                                                                                   | Handles are seized in places.                                                                                                                                         |                                                                                     |                                          |

## SINGLE SURVEY

|                                                                                                                             |                                                                                                                                                                                                                                                                                                                    |
|-----------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <b>External decorations</b>               |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | Decoration to timber fascias and timber doors, and the external walls, is extensively weathered.                                                                                                                                                                                                                   |
|  <b>Conservatories / porches</b>           |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | <p>Porches to the north and south elevations are both in extremely poor condition, with dangerous blockwork and holes in walls noted.</p> <p>These porches are currently dangerous and should be safely taken down and removed as soon as possible.</p>                                                            |
|  <b>Communal areas</b>                     |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 2                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | Shared access road is overgrown.                                                                                                                                                                                                                                                                                   |
|  <b>Garages and permanent outbuildings</b> |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | <p>The store to the eastern elevation of the house, and the detached store, are both in very poor condition, and should be removed safely as soon as possible.</p> <p>Note: the fibre cement sheets to the outbuildings may contain asbestos. This should be tested and removed and disposed of appropriately.</p> |
|  <b>Outside areas and boundaries</b>     |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | <p>Post &amp; wire fencing is in poor condition.</p> <p>The outside areas are extremely untidy and unsafe with widespread disposed materials. This constitutes a risk, as this is unsafe to access and will be a hazard in high winds. This will also be contributing to the rodent infestation issue.</p>         |
|  <b>Ceilings</b>                         |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | The ceiling linings are in very poor condition, with damaged and damp areas noted.                                                                                                                                                                                                                                 |
|  <b>Internal walls</b>                   |                                                                                                                                                                                                                                                                                                                    |
| Repair category:                                                                                                            | 3                                                                                                                                                                                                                                                                                                                  |
| Notes:                                                                                                                      | The internal wall linings are in poor condition, with damaged and damp areas noted.                                                                                                                                                                                                                                |

## SINGLE SURVEY

|                                                                                     |                                                                                                             |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|
|    | <b>Floors including sub-floors</b>                                                                          |
| Repair category:                                                                    | 1                                                                                                           |
| Notes:                                                                              | No significant defects noted.                                                                               |
|    | <b>Internal joinery and kitchen fittings</b>                                                                |
| Repair category:                                                                    | 3                                                                                                           |
| Notes:                                                                              | Generally basic and in very poor condition.<br>Joinery missing in places.                                   |
|    | <b>Chimney breasts and fireplaces</b>                                                                       |
| Repair category:                                                                    | N/A                                                                                                         |
| Notes:                                                                              | There are no chimney breasts or fireplaces.                                                                 |
|    | <b>Internal decorations</b>                                                                                 |
| Repair category:                                                                    | 3                                                                                                           |
| Notes:                                                                              | Generally very poor condition.                                                                              |
|   | <b>Cellars</b>                                                                                              |
| Repair category:                                                                    | N/A                                                                                                         |
| Notes:                                                                              | There are no cellars.                                                                                       |
|  | <b>Electricity</b>                                                                                          |
| Repair category:                                                                    | 2                                                                                                           |
| Notes:                                                                              | The electrical installation was not tested.                                                                 |
|  | <b>Gas</b>                                                                                                  |
| Repair category:                                                                    | N/A                                                                                                         |
| Notes:                                                                              | There is no gas installation.                                                                               |
|  | <b>Water, plumbing and bathroom fittings</b>                                                                |
| Repair category:                                                                    | 2                                                                                                           |
| Notes:                                                                              | The plumbing installation was not tested.<br>The cold water header tank in the roof space is not insulated. |
|  | <b>Heating and hot water</b>                                                                                |
| Repair category:                                                                    | 1                                                                                                           |
| Notes:                                                                              | The heating and hot water systems were not tested.                                                          |

## SINGLE SURVEY



### Drainage

|                  |                                                                                        |
|------------------|----------------------------------------------------------------------------------------|
| Repair category: | 2                                                                                      |
| Notes:           | No access to inspect the underground drainage system.<br>Broken drainage covers noted. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

|                                       |     |
|---------------------------------------|-----|
| Structural movement                   | 2   |
| Dampness, rot and infestation         | 3   |
| Chimney stacks                        | 3   |
| Roofing including roof space          | 2   |
| Rainwater fittings                    | 3   |
| Main walls                            | 3   |
| Windows, external doors and joinery   | 2   |
| External decorations                  | 3   |
| Conservatories / porches              | 3   |
| Communal areas                        | 2   |
| Garages and permanent outbuildings    | 3   |
| Outside areas and boundaries          | 3   |
| Ceilings                              | 3   |
| Internal walls                        | 3   |
| Floors including sub-floors           | 1   |
| Internal joinery and kitchen fittings | 3   |
| Chimney breasts and fireplaces        | N/A |
| Internal decorations                  | 3   |
| Cellars                               | N/A |
| Electricity                           | 2   |
| Gas                                   | N/A |
| Water, plumbing and bathroom fittings | 2   |
| Heating and hot water                 | 1   |
| Drainage                              | 2   |

## Repair Categories

### Category 3:

Urgent Repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### Category 2:

Repairs or replacement requiring future attention, but estimates are still advised.

### Category 1:

No immediate action or repair is needed.

## Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

## Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. ACCESSIBILITY INFORMATION

#### Guidance Notes on Accessibility Information

**Three steps or fewer to a main entrance door of the property:** In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

**Unrestricted parking within 25 metres:** For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes: Parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

|                                                                                               |               |
|-----------------------------------------------------------------------------------------------|---------------|
| <b>1. Which floor(s) is the living accommodation on?</b>                                      | <b>Ground</b> |
| <b>2. Are there three steps or fewer to a main entrance door of the property?</b>             | <b>Yes</b>    |
| <b>3. Is there a lift to the main entrance door of the property?</b>                          | <b>No</b>     |
| <b>4. Are all door openings greater than 750mm?</b>                                           | <b>No</b>     |
| <b>5. Is there a toilet on the same level as the living room and kitchen?</b>                 | <b>Yes</b>    |
| <b>6. Is there a toilet on the same level as a bedroom?</b>                                   | <b>Yes</b>    |
| <b>7. Are all rooms on the same level with no internal steps or stairs?</b>                   | <b>Yes</b>    |
| <b>8. Is there unrestricted parking within 25 metres of an entrance door to the building?</b> | <b>Yes</b>    |



#### 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

**Matters for a solicitor or licensed conveyancer**

Check

- Rights and responsibilities for mutual parts, boundaries etc.
- That the Title is clean and Heritable with no onerous burdens or conditions.

**Estimated re-instatement cost for insurance purposes**


£350,000 (Three Hundred and Fifty Thousand Pounds).

**Valuation and market comments**

The market value of the property as described in this report is £75,000 (Seventy-Five Thousand Pounds).

This figure assumes vacant possession and that the property is unaffected by adverse planning proposals, onerous burdens, title restrictions and servitude rights.

**Signed**



**Surveyors Name**

Billy Groundwater, AssocRICS

**Company Name**

Orkney Surveying Services

**Address:**

Castlehowe, Sower Road, Orphir, Orkney, KW17 2RE

**Date of report:**

11<sup>th</sup> November 2025

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

BURNSIDE, CUSBAY ROAD, EDAY, ORKNEY, KW17 2AB

**Dwelling type:** Detached bungalow  
**Date of assessment:** 28 October 2025  
**Date of certificate:** 02 November 2025  
**Total floor area:** 75 m<sup>2</sup>  
**Primary Energy Indicator:** 463 kWh/m<sup>2</sup>/year

**Reference number:** 6990-0485-0322-1121-1053  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Electric storage heaters


## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

|                                                   |         |                                                      |
|---------------------------------------------------|---------|------------------------------------------------------|
| Estimated energy costs for your home for 3 years* | £15,756 | See your recommendations report for more information |
| Over 3 years you could save*                      | £8,265  |                                                      |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Not energy efficient - higher running costs

| Current | Potential |
|---------|-----------|
| 33      | 82        |


## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band F (33)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Very environmentally friendly - lower CO<sub>2</sub> emissions



Not environmentally friendly - higher CO<sub>2</sub> emissions

| Current | Potential |
|---------|-----------|
| 67      | 91        |

## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (67)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

| Recommended measures                 | Indicative cost  | Typical savings over 3 years |
|--------------------------------------|------------------|------------------------------|
| 1 Increase loft insulation to 270 mm | £900 - £1,200    | £2592.00                     |
| 2 Cavity wall insulation             | £900 - £1,500    | £1332.00                     |
| 3 Internal wall insulation           | £7,500 - £11,000 | £1365.00                     |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description                                    | Energy Efficiency | Environmental |
|-----------------------|------------------------------------------------|-------------------|---------------|
| Walls                 | Sandstone, as built, no insulation (assumed)   | ★★☆☆☆             | ★★☆☆☆         |
|                       | Cavity wall, as built, no insulation (assumed) | ★★☆☆☆             | ★★☆☆☆         |
| Roof                  | Pitched, 25 mm loft insulation                 | ★★☆☆☆             | ★★☆☆☆         |
| Floor                 | Solid, no insulation (assumed)                 | —                 | —             |
| Windows               | Fully double glazed                            | ★★☆☆☆             | ★★☆☆☆         |
| Main heating          | Electric storage heaters                       | ★★★★☆             | ★★★★★         |
| Main heating controls | Automatic charge control                       | ★★★★☆             | ★★★★☆         |
| Secondary heating     | Room heaters, electric                         | —                 | —             |
| Hot water             | Electric immersion, off-peak                   | ★★★★☆             | ★★★★★         |
| Lighting              | Below average lighting efficiency              | ★☆☆☆☆             | ★☆☆☆☆         |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 45 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.4 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.3 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

## Estimated energy costs for this home

|               | Current energy costs | Potential energy costs | Potential future savings                                                            |
|---------------|----------------------|------------------------|-------------------------------------------------------------------------------------|
| Heating       | £13,845 over 3 years | £6,273 over 3 years    |  |
| Hot water     | £1,350 over 3 years  | £1,041 over 3 years    |                                                                                     |
| Lighting      | £561 over 3 years    | £177 over 3 years      |                                                                                     |
| <b>Totals</b> | <b>£15,756</b>       | <b>£7,491</b>          |                                                                                     |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures                                              | Indicative cost  | Typical saving per year | Rating after improvement |             |
|-------------------------------------------------------------------|------------------|-------------------------|--------------------------|-------------|
|                                                                   |                  |                         | Energy                   | Environment |
| 1 Increase loft insulation to 270 mm                              | £900 - £1,200    | £864                    | E 42                     | C 73        |
| 2 Cavity wall insulation                                          | £900 - £1,500    | £444                    | E 48                     | C 76        |
| 3 Internal wall insulation                                        | £7,500 - £11,000 | £455                    | E 54                     | C 79        |
| 4 Floor insulation (solid floor)                                  | £5,000 - £10,000 | £471                    | D 60                     | B 82        |
| 5 Low energy lighting for all fixed outlets                       | £180 - £210      | £71                     | D 62                     | B 82        |
| 6 High heat retention storage heaters and dual immersion cylinder | £800 - £1,600    | £296                    | D 65                     | B 84        |
| 7 Solar water heating                                             | £4,000 - £7,000  | £82                     | D 66                     | B 85        |
| 8 High performance external doors                                 | £1,800 - £2,400  | £73                     | D 67                     | B 85        |
| 9 Solar photovoltaic panels, 2.5 kWp                              | £8,000 - £10,000 | £262                    | C 74                     | B 87        |
| 10 Wind turbine                                                   | £5,000 - £20,000 | £575                    | B 82                     | B 91        |

### Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- External insulation with cavity wall insulation
- Biomass boiler (Exempted Appliance if in Smoke Control Area)

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).



## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Loft insulation

Loft insulation laid in the loft space or between roof rafters to a depth of at least 270 mm will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation should not be placed below any cold water storage tank, any such tank should also be insulated on its sides and top, and there should be boarding on battens over the insulation to provide safe access between the loft hatch and the cold water tank. The insulation can be installed by professional contractors but also by a capable DIY enthusiast. Loose granules may be used instead of insulation quilt; this form of loft insulation can be blown into place and can be useful where access is difficult. The loft space must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about loft insulation and details of local contractors can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)).

### 2 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)).

### 3 Internal wall insulation

Internal wall insulation involves adding a layer of insulation to the inside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. Further information can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)).

### 4 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including [www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation](http://www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation). Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

### 5 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (<http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting>).

### 6 High heat retention storage heaters

Modern storage heaters have better insulation and are easier to control than the older type in this property. Ask for a quotation for new, high heat retention heaters with automatic charge and output controls. A dual-immersion cylinder, which can be installed at the same time, will provide cheaper hot water than the system currently installed. Installations should be in accordance with the current regulations covering electrical wiring. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.

## 7 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## 8 High performance external doors

High performance external doors contain insulation and lose heat at about half the rate of conventional external doors. Building regulations generally apply to this work, so it is best to check this your local authority building standards department.

## 9 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## 10 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 19,627.57         | N/A                       | N/A                              | N/A                             |
| Water heating (kWh per year) | 1,956.35          |                           |                                  |                                 |

## Addendum

This dwelling has stone walls and may be exposed to wind driven rain and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.



## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

|                             |                                                                              |
|-----------------------------|------------------------------------------------------------------------------|
| Assessor's name:            | Mr. William Groundwater                                                      |
| Assessor membership number: | EES/019552                                                                   |
| Company name/trading name:  | Orkney Surveying Services                                                    |
| Address:                    | Castlehowe Sower Road<br>Orphir<br>Orkney Islands<br>Orkney<br>KW17 2RE      |
| Phone number:               | 01856 811765                                                                 |
| Email address:              | <a href="mailto:billy@orkneysurveying.co.uk">billy@orkneysurveying.co.uk</a> |
| Related party disclosure:   | No related party                                                             |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).



### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT



# property questionnaire

|                                                  |                                                     |
|--------------------------------------------------|-----------------------------------------------------|
| <b>Property address</b>                          | BURNSIDE<br>EDAY<br>ORKNEY<br>KW17 2AB              |
| <b>Seller(s)</b>                                 | SERENA SUTHERLAND MS<br>GUARDIAN OF FLORENCE SUTERS |
| <b>Completion date of property questionnaire</b> | 04.11.2025                                          |

## Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

## Information to be given to prospective buyer(s)

|    |                                                                                                                                      |
|----|--------------------------------------------------------------------------------------------------------------------------------------|
| 1. | <b>Length of ownership</b>                                                                                                           |
|    | How long have you owned the property? 22 YEARS.                                                                                      |
| 2. | <b>Council tax</b>                                                                                                                   |
|    | Which Council Tax band is your property in? (Please circle)<br><input checked="" type="radio"/> A    B    C    D    E    F    G    H |
| 3. | <b>Parking</b>                                                                                                                       |

# property questionnaire

|    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                  |
|----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|
|    | <p><b>What are the arrangements for parking at your property?</b></p> <p><b>(Please tick all that apply)</b></p> <ul style="list-style-type: none"> <li>• Garage <input type="checkbox"/></li> <li>• Allocated parking space <input type="checkbox"/></li> <li>• Driveway <input checked="" type="checkbox"/></li> <li>• Shared parking <input type="checkbox"/></li> <li>• On street <input type="checkbox"/></li> <li>• Resident permit <input type="checkbox"/></li> <li>• Metered parking <input type="text"/></li> <li>• Other (please specify):</li> </ul> |                                                  |
| 4. | <b>Conservation area</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                                  |
|    | <p><b>Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?</b></p>                                                                                                                                                                                                                                                                                                                                                 | <p><b>Yes/No/Don't know</b></p> <p><b>No</b></p> |

|    |                                                                                                                                                                                                                                                                                                               |                                            |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| 5. | <b>Listed buildings</b>                                                                                                                                                                                                                                                                                       |                                            |
|    | <p><b>Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?</b></p>                                                                                                                              | <p><b>Yes/No</b></p> <p><b>No</b></p>      |
| 6. | <b>Alterations/additions/extensions</b>                                                                                                                                                                                                                                                                       |                                            |
| a. | <p><b>(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?</b></p> <p><b><u>If you have answered yes</u>, please describe below the changes which you have made:</b></p> | <p><b>Yes/No</b></p> <p><b>UNKNOWN</b></p> |

# property questionnaire

|    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                     |
|----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|
|    | <p><b>(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?</b></p> <p><b><u>If you have answered yes</u>, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</b></p> <p><b>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:</b></p> | <p><b>Yes/No</b></p> <p>UNKNOWN</p> |
| b. | <p><b>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</b></p> <p><b><u>If you have answered yes</u>, please answer the three questions below:</b></p>                                                                                                                                                                                                                                                                                | <p><b>Yes/No</b></p> <p>UNKNOWN</p> |
|    | <p><b>(i) Were the replacements the same shape and type as the ones you replaced?</b></p>                                                                                                                                                                                                                                                                                                                                                                                               | <p><b>Yes/No</b></p> <p>UNKNOWN</p> |
|    | <p><b>(ii) Did this work involve any changes to the window or door openings?</b></p>                                                                                                                                                                                                                                                                                                                                                                                                    | <p><b>Yes/No</b></p> <p>UNKNOWN</p> |
|    | <p><b>(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):</b></p> <p>UNKNOWN</p> <p><b>Please give any guarantees which you received for this work to your solicitor or estate agent.</b></p>                                                                                                                                                                                                             |                                     |



# property questionnaire

|           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                          |
|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| <b>7.</b> | <b>Central heating</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                          |
| <b>a.</b> | <p><b>Is there a central heating system in your property?</b><br/>         (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).</p> <p><u>If you have answered yes or partial</u> – what kind of central heating is there?<br/>         (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).</p> <p><u>If you have answered yes</u>, please answer the three questions below:</p> | <b>Yes/No/ Partial</b>                                   |
|           | <b>i) When was your central heating system or partial central heating system installed?</b>                                                                                                                                                                                                                                                                                                                                                                                                                                  | UNKNOWN                                                  |
|           | <p><b>(ii) Do you have a maintenance contract for the central heating system?</b></p> <p><u>If you have answered yes</u>, please give details of the company with which you have a maintenance contract:</p>                                                                                                                                                                                                                                                                                                                 | <b>Yes/No</b><br>UNKNOWN                                 |
|           | <b>(iii) When was your maintenance agreement last renewed?</b><br>(Please provide the month and year).                                                                                                                                                                                                                                                                                                                                                                                                                       | UNKNOWN                                                  |
| <b>8.</b> | <b>Energy Performance Certificate</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                                          |
|           | <b>Does your property have an Energy Performance Certificate which is less than 0 years old?</b>                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Yes/No</b><br>UNKNOWN                                 |
| <b>9.</b> | <b>Issues that may have affected your property</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                          |
| <b>a.</b> | <p><b>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</b></p> <p><u>If you have answered yes</u>, is the damage the subject of any outstanding insurance claim?</p>                                                                                                                                                                                                                                                                                               | <b>Yes/No</b><br>UNKNOWN<br><br><b>Yes/No</b><br>UNKNOWN |
| <b>b.</b> | <p><b>Are you aware of the existence of asbestos in your property?</b></p> <p><u>If you have answered yes</u>, please give details:</p>                                                                                                                                                                                                                                                                                                                                                                                      | <b>Yes/No</b>                                            |
| <b>0.</b> | <b>Services</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                          |

# property questionnaire

a. Please tick which services are connected to your property and give details of the supplier:

| Services                            | Connected | Supplier       |
|-------------------------------------|-----------|----------------|
| Gas or liquid petroleum gas         | UNKNOWN   | NA             |
| Water mains or private water supply | YES       | SCOTTISH WATER |
| Electricity                         | YES       | UNKNOWN        |
| Mains drainage                      | YES       | SCOTTISH WATER |
| Telephone                           | UNKNOWN   | NA             |
| Cable TV or satellite               | UNKNOWN   | NA             |
| Broadband                           | UNKNOWN   | NA             |

b. Is there a septic tank system at your property?

Yes/No

If you have answered yes, please answer the two questions below:

UNKNOWN

(i) Do you have appropriate consents for the discharge from your septic tank?

Yes/No/  
Don't know

UNKNOWN

(ii) Do you have a maintenance contract for your septic tank?

Yes/No

If you have answered yes, please give details of the company with which you have a maintenance contract:

UNKNOWN

Responsibilities for shared or common areas

# property questionnaire

|                                              |                                                                                                                                                                                                                                                                                     |                                                                                               |
|----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| a.                                           | <p>Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?</p> <p><u>If you have answered yes, please give details:</u></p>                                           | <p><del>Yes</del>/No/<br/>Don't know</p> <p>HALF SHARE OF<br/>TRACK ROAD<br/>MAINTENANCE.</p> |
| b.                                           | <p>Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?</p> <p><u>If you have answered yes, please give details:</u></p>                                                                                          | <p><del>Yes</del>/No/<br/>Not applicable</p>                                                  |
| c.                                           | <p>Has there been any major repair or replacement of any part of the roof during the time you have owned the property?</p>                                                                                                                                                          | <p><del>Yes</del>/No<br/>UNKNOWN</p>                                                          |
| d.                                           | <p>Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?</p> <p><u>If you have answered yes, please give details:</u></p>                                                                   | <p><del>Yes</del>/No</p> <p>SHARED ACCESS<br/>TRACK ROAD</p>                                  |
| e.                                           | <p>As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?</p> <p><u>If you have answered yes, please give details:</u></p>                                         | <p><del>Yes</del>/No</p> <p>SHARED ACCESS<br/>TRACK ROAD</p>                                  |
| f.                                           | <p>As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)</p> <p><u>If you have answered yes, please give details:</u></p> | <p><del>Yes</del>/No</p>                                                                      |
| <p>Charges associated with your property</p> |                                                                                                                                                                                                                                                                                     |                                                                                               |
| a.                                           | <p>Is there a factor or property manager for your property?</p> <p><u>If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:</u></p>                                                                          | <p><del>Yes</del>/No</p>                                                                      |



# property questionnaire

|    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                             |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| b. | <p>Is there a common buildings insurance policy?</p> <p><u>If you have answered yes</u>, is the cost of the insurance included in your monthly/annual factor's charges?</p>                                                                                                                                                                                                                                                                                                                                                                                                           | <p>Yes/No/<br/>Don't know</p> <p>Yes/No/<br/>Don't know</p> |
| c. | <p>Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.</p> <p>UNKNOWN</p>                                                                                                                                                                                                                                                                                                                                                              |                                                             |
| 3. | Specialist works                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                             |
| a. | <p>As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?</p> <p><u>If you have answered yes</u>, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.</p>                                                                                                                                                                                                                                                        | <p>Yes/No</p> <p>UNKNOWN</p>                                |
| b. | <p>As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?</p> <p><u>If you have answered yes</u>, please give details:</p>                                                                                                                                                                                                                                                                                                                                                                                          | <p>Yes/No</p> <p>UNKNOWN</p>                                |
| c. | <p><u>If you have answered yes</u> to 3(a) or (b), do you have any guarantees relating to this work?</p> <p><u>If you have answered yes</u>, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:</p> | <p>Yes/No</p> <p>NA</p>                                     |



# property questionnaire

|           |                                                                                                                                                                                             |    |     |            |                  |                                                                                 |
|-----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|-----|------------|------------------|---------------------------------------------------------------------------------|
| <b>4.</b> | <b>Guarantees</b>                                                                                                                                                                           |    |     |            |                  |                                                                                 |
| <b>a.</b> | <b>Are there any guarantees or warranties for any of the following:</b>                                                                                                                     |    |     |            |                  |                                                                                 |
| (i)       | Electrical work                                                                                                                                                                             | No | Yes | Don't know | With title deeds | Lost                                                                            |
| (ii)      | Roofing                                                                                                                                                                                     | No | Yes | Don't know | With title deeds | Lost                                                                            |
| (iii)     | Central heating                                                                                                                                                                             | No | Yes | Don't know | With title deeds | Lost                                                                            |
| (iv)      | National House Building Council (NHBC)                                                                                                                                                      | No | Yes | Don't know | With title deeds | Lost                                                                            |
| (v)       | Damp course                                                                                                                                                                                 | No | Yes | Don't know | With title deeds | Lost                                                                            |
| (vi)      | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)                                                                                      | No | Yes | Don't know | With title deeds | Lost                                                                            |
| <b>b.</b> | <b>If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):</b><br><div style="text-align: right;">N/A</div> |    |     |            |                  |                                                                                 |
| <b>c.</b> | <b>Are there any outstanding claims under any of the guarantees listed above?</b><br><b>If you have answered yes, please give details:</b>                                                  |    |     |            |                  | <b>Yes/No</b><br><br><div style="text-align: right;">N/A</div>                  |
| <b>5.</b> | <b>Boundaries</b>                                                                                                                                                                           |    |     |            |                  |                                                                                 |
|           | <b>So far as you are aware, has any boundary of your property been moved in the last 0 years?</b><br><b>If you have answered yes, please give details:</b>                                  |    |     |            |                  | <b>Yes/No/Don't know</b><br><div style="text-align: right;">No/Don't know</div> |

**Declaration by the seller(s)/or other authorised body or person(s)**

# property questionnaire

|                                                                                                                                                                                                                            |                                                                                            |                          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|--------------------------|
| <b>6.</b>                                                                                                                                                                                                                  | <b>Notices that affect your property</b>                                                   |                          |
| <b>In the past three years have you ever received a notice:</b>                                                                                                                                                            |                                                                                            |                          |
| <b>a.</b>                                                                                                                                                                                                                  | <b>advising that the owner of a neighbouring property has made a planning application?</b> | <b>Yes/No</b><br>UNKNOWN |
| <b>b.</b>                                                                                                                                                                                                                  | <b>that affects your property in some other way?</b>                                       | <b>Yes/No</b><br>UNKNOWN |
| <b>c.</b>                                                                                                                                                                                                                  | <b>that requires you to do any maintenance, repairs or improvements to your property?</b>  | <b>Yes/No</b><br>UNKNOWN |
| <b>If you have answered yes to any of a–c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.</b> |                                                                                            | N/A                      |

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) : Signed by:  
serena sutherland  
1F1F4A48EC424F5...

Date:

07-11-2025 | 10:33 AM GMT

### PART 1 – GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.<sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box. ☐

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The/-

---

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### **1.3 LIABILITY**

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

### **1.4 INTELLECTUAL PROPERTY**

Any intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

### **1.5 PAYMENT**

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

### **1.6 CANCELLATION**

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection. /-

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

### 1.7 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

### 1.8 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Market Value" is *The estimated amount for which a Property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member of partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

---

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct

### PART 2 – DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyors opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

**WARNING: /-**



**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable. Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

*Market Value" The estimated amount for which a property should exchange on the date of valuation within a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion.* In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc and to use communal grounds, parking areas, and other facilities;
- \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" /-

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.